ECS Configuration Change Request					Page 1 of Page(s)			ge(s)	
1. Originator	2. Log Date:	3. CCR #:	4.	Rev:	5. Tel:	(	6. Rm #:	7. Dept.	
Robert Cole	9/5/02	02-0748		_	301-925-0799	:	2110C	SE/HW	
8. CCR Title: Install RDAC ver 08.00.02.01 and Santricity ver 08.00.G2.01 on p0sas01									
9. Originator Signature/Date			10. Class		11. Type:	12.	<b>12. Need Date:</b> 9/30/02		
Robert Cole /s/ 9/4/02			IN	CCR					
13. Office Manager Signature/Date			14. Category o		_		<b>15. Priority: (</b> If "Emergency" fill in Block 27).		
Randy Haynes /s/ 9/4/02				Update ECS Baseline Doc.			Routine		
<b>16. Documentation/Drawing</b> 910-TDA-003, 920-TDP-002,	7. Schedule 18. CI(s) Affected:SYN npact:			d:SYN					
19. Release Affected by this Change: 20. Date due				o Customer: 21. Estimated Cost:					
N/A				None - Under 100K					
22. Source Reference: ☐NCR (attach) ☐Action Item ☐Tech Ref. ☐GSFC ☐Other:									
23. Problem: (use additional Sheets if necessary)  A new version (08.00.02.01) of Redundant Disk Array Controller (RDAC) is required with the D178 RAID controllers that were recently deployed to some DAACs as part of the Synergy III procurement. Although our SAN vendor, STK, has performed this installation at the affected sites, no PSR yet exists for this version of RDAC.									
24. Proposed Solution: (use additional sheets if necessary) Install RDAC version 08.00.02.01 on p0sas01 to support the generation of a PSR for this version. This version of RDAC requires version 08.00.G2.01 of Santricity Storage Manager (PSR 914-TDA-206). Both of these COTS versions are compatible with the PVC RAID hardware.									
25. Alternate Solution: (use additional sheets if necessary) Opt to not deliver a PSR for the new version of RDAC.									
26. Consequences if Change(s) are not approved: (use additional sheets if necessary) It will not be possible to generate a PSR for this COTS product due to lack of an environment to capture installation instructions and perform testing.									
27. Justification for Emergency (If Block 15 is "Emergency"):									
28. Site(s) Affected: ☐EDF ☐PVC ☐VATC ☐EDC ☐ GSFC ☐LaRC ☐NSIDC ☐SMC ☐AK ☐JPL ☐EOC ☐ IDG Test Cell ☐Other									
29. Board Comments:			,	30. W	ork Assigned T	o: :	31. CCR C	losed Date:	
32. EDF/SCDV CCB Chair (	_	isposition: A	pproved A	App/Co	om. Disapproved	iW t	thdraw Fw	vd/ESDIS	
Byron V. Peters /s/ 9	<b>9/11/02</b> ER		vd/FCS						
33. M&O CCB Chair (Sign/l	Date): Di	i <b>sposition:</b> Ap	pproved App/Com. Disapproved Withdraw Fwd/ESDIS ERB						
34. ECS CCB Chair (Sign/D	Date): Dis	sposition: Ap		p/Con	n. Disapproved	l Wit	hdraw Fw	d/ESDIS ERB	
(- <b>.9.4</b> -	,	Fwd/ESDIS							

CM01JA00 Revised 10/15/01 ECS/EDF/SCDV/M&O